

PEX Crimp Fittings

Crimp x Male Sweat Adapters — for connecting PEX to sweat fittings or manifolds.



Male Sweat

DESCRIPTION	QTY	MODEL #	ORDER #	WT. (lbs)
3/8" Crimp x 1/2" Male Sweat Adapter	10	PC637X-10	81001027	1
1/2" Crimp x 1/2" Male Sweat Adapter	10	PC650X-10	81001030	1
5/8" Crimp x 1/2" Male Sweat Adapter	10	PC660X-10	81003685	1
5/8" Crimp x 3/4" Male Sweat Adapter	10	PC670X-10	81003427	1
3/4" Crimp x 3/4" Male Sweat Adapter	10	PC675X-10	81001034	2
1" Crimp x 1" Male Sweat Adapter	10	PC700X-10	81001037	2
1-1/4" Crimp x 1-1/4" Male Sweat Adapter	10	PC725X-10	81005381	3
NEW 1-1/2" Crimp x 1-1/2" Male Sweat Adapter	10	PC795X-10	81011130	4

Note: All 1-1/4" crimp fittings are equipped with O-rings. 1-1/2" CrimpRings require a Power Crimp Tool. 3/8" - 1" PEX fittings can be used with either Crimp or Cinch connector. 1-1/4" and larger can only be used with Crimp connectors.

Crimp x Female Sweat Adapters — for connecting PEX to sweat fittings or manifolds.



Female Sweat

DESCRIPTION	QTY	MODEL #	ORDER #	WT. (lbs)
1/2" Crimp x 1/2" Female Sweat Adapter	10	PC750X-10	81001040	1
3/4" Crimp x 3/4" Female Sweat Adapter	10	PC775X-10	81001043	1
1" Crimp x 1" Female Sweat Adapter	10	PC780X-10	81003031	2
1-1/4" Crimp x 1-1/4" Female Sweat Adapter	10	PC785X-10	81009387	2
NEW 1-1/2" Crimp x 1-1/2" Female Sweat Adapter	10	PC790X-10	81011131	3

Note: All 1-1/4" crimp fittings are equipped with O-rings. 1-1/2" CrimpRings require a Power Crimp Tool.

Crimp x Male NPT Adapters — for connecting PEX to female fittings and valves.



DESCRIPTION	QTY	MODEL #	ORDER #	WT. (lbs)
3/8" Crimp x 1/2" MPT Adapter	10	PCMC23X-10	81005382	2
1/2" Crimp x 1/2" MPT Adapter	10	PCMC33X-10	81005383	2
1/2" Crimp x 3/4" MPT Adapter	10	PCMC34X-10	81005384	2
5/8" Crimp x 3/4" MPT Adapter	10	PCMC64X-10	81005385	2
3/4" Crimp x 1/2" MPT Adapter	10	PCMC43X-10	81005386	2
3/4" Crimp x 3/4" MPT Adapter	10	PCMC44X-10	81005387	2
1" Crimp x 1" MPT Adapter	10	PCMC55X-10	81005388	3
1-1/4" Crimp x 1-1/4" MPT Adapter	10	PCMC78X-10	81005389	3
NEW 1-1/2" Crimp x 1-1/2" MPT Adapter	10	PCMC99X-10	81011132	4


Note: All 1-1/4" crimp fittings are equipped with O-rings. 1-1/2" CrimpRings require a Power Crimp Tool.

Crimp x Male NPT Elbows



DESCRIPTION	QTY	MODEL #	ORDER #	WT. (lbs)
1/2" Crimp x 1/2" MPT Elbow	10	PCE33BTX-10	81005390	2
1/2" Crimp x 3/4" MPT Elbow	10	PCE34BTX-10	81005391	3
3/4" Crimp x 3/4" MPT Elbow	10	PCE44BTX-10	81005392	3

Crimp x Female Sweat Elbow



Female Sweat

DESCRIPTION	QTY	MODEL #	ORDER #	WT. (lbs)
1/2" Crimp x 3/4" Female Sweat Elbow	10	PCE34-10	81005393	3
5/8" Crimp x 3/4" Female Sweat Elbow	10	PCE64-10	81004786	3
3/4" Crimp x 3/4" Female Sweat Elbow	10	PCE44-10	81005394	3

Use these **Crimp x Sweat Elbow Fittings** to speed the connection of PEX supply lines to baseboard and hydro-air units.