

REPAIR PARTS

LABORATORY PRODUCTS & DRENCH HOSES

SE-570, SE-571, SE-572, SE-573, SE-575, SE-568

PART #	PRICE	PRODUCT DESCRIPTION
RPG05-0673	\$ 15.60	Internal o-rings, screws for valve
RPG05-0714	\$ 70.00	Bullhorn assembly with aerated sprays
RPG05-1177	\$ 90.00	Aerator replacement group (6 each)
RPG07-0104	\$ 55.00	Flip top cap replacements (20 per bag)
RPG20-1996	\$ 147.00	Ball valve assembly (SE-572)
RPG20-2015	\$ 541.00	Swing down eyewash valve assembly
RPG38-0379	\$ 69.00	Spray head assembly with aerators (4 per bag)
RPG38-0421	\$ 156.00	Non-aerated spray head assembly

DRENCH HOSES

PART #	PRICE	PRODUCT DESCRIPTION
G20-0584-PC	\$ 140.00	Drench hose self closing valve repair group (SE-920)
RPG05-1177	\$ 90.00	Aerator replacement group (6 each)
RPG07-0104	\$ 55.00	Flip top cap replacements (20 per bag)
RPG20-1742	\$ 160.00	Drench hose stay open valve repair group (SE-927)
RPG38-0379	\$ 69.00	Aerated spray head assembly for SE-580/582 (4 each)
RPG38-0390	\$ 64.00	Non-aerated spray head assembly (4 per bag)

IMAGES



RPG05-0673



RPG20-2015



RPG38-0421



RPG07-0104



RPG38-0390



G20-0584-PC



RPG38-0417



RPG20-1996




RPG05-0714



RPG05-1177



RPG20-1742



RPG20-2010-RCP



RPG38-0379